

FIG. 1b




FIG. 1g




FIG. 2a




FIG. 2b




FIG. 2c

FIG.3A	FIG.3C	FIG.3E
FIG.3B	FIG.3D	FIG.3F

FIG.3




FIG.3a




FIG.3b




FIG.3c







FIG.3d





AVX/ELCO 086210010800

FIG.3f




FIG. 4a




FIG. 4b




FIG. 5




FIG. 6






FIG. 7






FIG.9




FIG.10




FIG.11




FIG.12




FIG.14




FIG.15




FIG.16




FIG.17